



Service Information  
No. SI-E4-007

Austro Engine GmbH  
Rudolf-Diesel-Strasse 11  
A-2700 Wiener Neustadt  
Tel: +43 2622 23000  
FAX: +43 2622 23000-2711

# SERVICE INFORMATION

## No. SI-E4-007

### 1. BASIC INFORMATION

#### 1.1. SUBJECT

Proper handling of turbo charger

#### 1.2. ENGINES AFFECTED

Type: E4, all models

Serial Number: All

#### 1.3. REASON

Improper handling of the turbo charger could subsequently lead to mechanical failure of the turbo charger.

#### 1.4. INFORMATION

Ensure proper and careful handling of the turbo charger when conducting maintenance works. Only use a rubber hammer when needed! Only gently tapping with the rubber hammer is allowed!

Replace the turbo charger in case of any damage caused by improper handling!

### 2. REMARKS

**NOTE:** SI are used only:

- To distribute information from Austro Engine GmbH to our customers.
- To distribute applicable information/documents from our suppliers to our customers with additional information.

First Issue Date			Rev. No.	Revision Date				Page
27	Sep	2016	---	---	---	---	1-1	