



Service Information
No. SI-E4-009

Austro Engine GmbH
Rudolf-Diesel-Strasse 11
2700 Wiener Neustadt
PHONE: +43 2622 23000
FAX: +43 2622 23000-2711

SERVICE INFORMATION

No. SI-E4-009

1. BASIC INFORMATION

1.1. SUBJECT

Two-Mass Flywheel and Hub

1.2. ENGINES AFFECTED

Type: E4
Model: E4, E4P
Serial Number(s): all

1.3. REASON

Austro Engine hereby advises to avoid the change of two-mass flywheels from twin engine aircraft (E4-B, E4-C and E4P-C engines) to single engine aircraft (E4-A engines).

1.4. INFORMATION

On twin-engine aircrafts (E4-B, E4-C, E4P-C) specially in flight training environment the wear and tear of the two-mass flywheel is slightly higher then on single-engine aircrafts (E4-A). Due to this fact it should not happen that a used two-mass flywheel, which was already mounted on a twin – engine aircraft, shall be used or mounted on a single engine aircraft. This procedure is to provide additional safety margin under all circumstances.

2. REMARKS

NOTE: SI are used only:

- To distribute information from Austro Engine GmbH to our customers.
- To distribute applicable information/documents from our suppliers to our customers with additional information.

First Issue Date			Rev. No.	Revision Date				Page
14	Jun	2017	--	--	---	----	1-1	